

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

ED649 AVENUE "V" PUMP STA.  
North AVENUE V  
1/2-1 BROOKLYN, NY  
0.955 mi.  
5045 ft. Site 6 of 8 in cluster ED

NY Spills S102147778  
N/A

Relative:  
Higher

Actual:  
13 ft.

SPILLS:

Name: AVENUE "V" PUMP STA.  
Address: AVENUE V  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9313625 / 1995-09-05  
Facility ID: 9313625  
Facility Type: ER  
DER Facility ID: 274051  
Site ID: 98195  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: E5  
SWIS: 2401  
Spill Date: 1994-02-19  
Investigator: RWAUSTIN  
Referred To: Not reported  
Reported to Dept: 1994-02-19  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Other  
Cleanup Ceased: 1995-09-05  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
  
Remediation Phase: 0  
Date Entered In Computer: 1994-05-26  
Spill Record Last Update: 2003-09-25  
Spiller Name: Not reported  
Spiller Company: NYC DEP  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
AUSTIN "  
Remarks: "SPDES."

All Materials:

Site ID: 98195  
Operable Unit ID: 992084  
Operable Unit: 01  
Material ID: 561623  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: -1.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported